
INSTRUCTIONS FOR SURFACE MOUNTING




DOWNHILL DAN 30, FLAT FREDDIE 30



2 MOUNT EXTRUSION, MAKE ELECTRICAL CONNECTION.

1. DRAW A STRAIGHT LINE ON THE MOUNTING SURFACE TO ALIGN MOUNTING CLIPS.

NOTE: MAXIMUM SPACE BETWEEN MOUNTING CLIPS SHOULD BE 400MM. MOUNTING CLIPS MUST BE POSITIONED WITHIN 100MM OF EACH END AND WITHIN 100MM EITHER SIDE OF A JOIN OR BEND. E.G. A 1000MM EXTRUSION SHOULD HAVE 3 MOUNTING POINTS, ONE CENTRED AND ONE EACH END WITHIN 100MM.





INSTRUCTIONS FOR SURFACE MOUNTING



DOWNHILL DAN 30, FLAT FREDDIE 30

